



# Sanitary Sewer Overflow Annual Report

Division of Surface Water

**Date:** 3-2-16  
**Facility name:** East Palestine WWTP  
**Ohio NPDES permit no.:** 3PD00042\*KD  
**Period covered by report:** 1-1-15 through 12-31-15


**Contact person**

**Name:** John Jurjavic  
**Title:** Water/Wastewater Supervisor  
**Mailing address:** 85 North Market St.  
 East Palestine, Ohio 44413  
**Telephone:** (330)426 - 7062  
**Email:** johnwwtp@sbcglobal.net

**Certification:**

*I certify under penalty of law that I have personally examined and am familiar with the information in this report and all attachments. Based on my inquiry of those persons immediately for obtaining the information contained in the report, I believe that the information is true, accurate, and complete.*

**Name** John Jurjavic **Title:** Water/Wastewater Supervisor  
**(typed):**

**Signature:**  **Date:** 3-2-16







Enter narrative analysis of WIB patterns by location, frequency and cause.

As in the past, our WIB occurrences are isolated locations throughout the system. Common causes are debris in the line, roots and occasionally grease.

An annual occurrence of WIB's would be the area of 500 W. Main St. This is due to extreme weather and depends on the amount of rain and how quickly it falls, and sometimes combined with snow melt. We are currently working with our engineers on a solution to this problem.