



Sanitary Sewer Overflow Annual Report

Division of Surface Water

Date: 9 February 2017
Facility name: East Palestine WWTP
Ohio NPDES permit no.: 3PD00042*LD
Period covered by report: 1-1-16 through 12-31-2016

Contact person

Name: John Jurjavcic
Title: Water/Wastewater Superintendent
Mailing address: 85 North Market St.
East Palestine, Oh 44413
Telephone: (330)426 - 7062
Email: johnwwtp@sbcglobal.net

Certification:

I certify under penalty of law that I have personally examined and am familiar with the information in this report and all attachments. Based on my inquiry of those persons immediately for obtaining the information contained in the report, I believe that the information is true, accurate, and complete.

Name (typed): John Jurjavcic **Title:** Water/Wastewater Superintenden

Signature:  **Date:** 9 Feb 2017

Enter narrative analysis of WIB patterns by location, frequency and cause.

Again, as in the past most of our WIB occurrences are isolated cases throughout the system. The most common causes are roots, debris in the line and occasionally grease.

As we had no real extreme weather events in 2016, the area of the 500 block of W. Main St. had no WIB occurrences as in past years. We did have three occurrences on E. Clark St. These were all due to debris and roots in the main line.